

| Line Item No. | Description of Item             | Unit of Measurement | Country of Origin | Amount    |
|---------------|---------------------------------|---------------------|-------------------|-----------|
| A             | <b>TOYOTA HILUX (OLD MODEL)</b> |                     |                   |           |
| (I)           | <b>PART 1: Vehicle Parts</b>    |                     |                   |           |
| 1.0           | Air Filter                      | number              | JAPAN             | 2800.000  |
| 2.0           | Acelater Cable                  | number              | JAPAN             | 20.000    |
| 3.0           | Arm Bush Lower                  | number              | JAPAN             | 1650.000  |
| 4.0           | Arm Bush Upper                  | number              | JAPAN             | 1650.000  |
| 5.0           | Arm Steering Knuckle LH/RH      | number              | JAPAN             | 250.000   |
| 6.0           | Arm Sub-Assy Pitman             | number              | JAPAN             | 400.000   |
| 7.0           | Axle Cone (Rear)                | number              | JAPAN             | 1800.000  |
| 8.0           | Axel Oil Seal                   | number              | JAPAN             | 750.000   |
| 9.0           | Axel Packing                    | number              | JAPAN             | 100.000   |
| 10.0          | Back Light Bulb (Single Point)  | number              | JAPAN             | 45.000    |
| 11.0          | Ball Joint Upper                | number              | JAPAN             | 3500.000  |
| 12.0          | Ball Joint Lower                | number              | JAPAN             | 3500.000  |
| 13.0          | Battery                         | number              | JAPAN             | 8500.000  |
| 14.0          | Bearing center support          | number              | JAPAN             | 250.000   |
| 15.0          | Bearing Diff. Inner             | number              | JAPAN             | 725.000   |
| 16.0          | Bearing Diff. Side Gear         | number              | JAPAN             | 950.000   |
| 17.0          | Bearing Front Wheel Inner       | number              | JAPAN             | 1250.000  |
| 18.0          | Bearing Front Wheel Outer       | number              | JAPAN             | 1450.000  |
| 19.0          | Bearing Rear Axle/Wheel         | number              | JAPAN             | 3800.000  |
| 20.0          | Bearing Set Connecting Rod      | number              | JAPAN             | 1100.000  |
| 21.0          | Bearing Set Crankshaft          | number              | JAPAN             | 650.000   |
| 22.0          | Bearing Tail Pinion Outer       | number              | JAPAN             | 450.000   |
| 23.0          | Brake Booster Assy              | number              | JAPAN             | 18000.000 |
| 24.0          | Brake Light Bulb (Double Point) | number              | JAPAN             | 45.000    |
| 25.0          | Brake Pad                       | number              | JAPAN             | 7800.000  |
| 26.0          | Brake Shoe Rear                 | number              | JAPAN             | 3800.000  |
| 27.0          | Bumper Light Assy (Front)       | number              | JAPAN             | 1500.000  |

|      |                                     |        |       |           |
|------|-------------------------------------|--------|-------|-----------|
| 28.0 | Bush Front Suspension (Lower LH)    | number | JAPAN | 1800.000  |
| 29.0 | Bush Front Suspension )Lower RH)    | number | JAPAN | 1800.000  |
| 30.0 | Bush Front Suspension (Upper RH/LH) | number | JAPAN | 1800.000  |
| 31.0 | Bush Rear Stabilizer                | number | JAPAN | 50.000    |
| 32.0 | Cam Shaft Bearing                   | number | JAPAN | 450.000   |
| 33.0 | Camp Bearing                        | number | JAPAN | 110.000   |
| 34.0 | Cap Assy. Fuel Filter               | number | JAPAN | 1650.000  |
| 35.0 | Center Bolt                         | number | JAPAN | 180.000   |
| 36.0 | Clutch Plate                        | number | JAPAN | 7800.000  |
| 37.0 | Clutch Release Bearing              | number | JAPAN | 0.000     |
| 38.0 | Bendix Pinion                       | number | JAPAN | 6800.000  |
| 40.0 | Cross Bearing                       | number | JAPAN | 3800.000  |
| 41.0 | CV Joint Boot (Outer)               | number | JAPAN | 1200.000  |
| 42.0 | CV Joint Boot (Inner)               | number | JAPAN | 2400.000  |
| 43.0 | Cylinder Assy Brake Master          | number | JAPAN | 18500.000 |
| 44.0 | Cylinder Assy Clutch Master         | number | JAPAN | 2800.000  |
| 45.0 | Cylinder Kit Brake Master           | number | JAPAN | 350.000   |
| 46.0 | Cylinder Kit Clutch Master          | number | JAPAN | 40.000    |
| 47.0 | Cylinder Kit Front Disc Brake       | number | JAPAN | 25.000    |
| 48.0 | Cylinder Kit Rear Wheel             | number | JAPAN | 100.000   |
| 49.0 | Deliver Valve                       | number | JAPAN | 100.000   |
| 50.0 | Diesel Filter                       | number | JAPAN | 1150.000  |
| 51.0 | Dust Guard                          | number | JAPAN | 750.000   |
| 52.0 | End Sub Assy Tie Rod (LH)           | number | JAPAN | 2800.000  |
| 53.0 | End Sub Assy Tie Rod (RH)           | number | JAPAN | 2800.000  |
| 54.0 | Engine Linner                       | number | JAPAN | 3000.000  |
| 55.0 | Fan Belt                            | number | JAPAN | 550.000   |
| 56.0 | Fan Sub-Assembly                    | number | JAPAN | 200.000   |
| 57.0 | Fly Ring Gear                       | number | JAPAN | 580.000   |
| 58.0 | Fog Lamp                            | number | JAPAN | 1200.000  |
| 59.0 | Foot Stand                          | number | JAPAN | 4500.000  |

|      |                                    |        |       |          |
|------|------------------------------------|--------|-------|----------|
| 60.0 | Four Wheel Bearing                 | number | JAPAN | 150.000  |
| 61.0 | Front Wheel Check Nut              | number | JAPAN | 250.000  |
| 62.0 | Front Wheel Checknut Lock          | number | JAPAN | 250.000  |
| 63.0 | Fuel Filter                        | number | JAPAN | 1150.000 |
| 64.0 | Fuel Tank                          | number | JAPAN | 120.000  |
| 65.0 | Gasket Engine Overhaul             | number | JAPAN | 7500.000 |
| 66.0 | Glass Back Light Assy LH/RH        | number | JAPAN | 35.000   |
| 67.0 | Glass Back Light LH/RH             | number | JAPAN | 35.000   |
| 68.0 | Glass Front Indicator LH/RH        | number | JAPAN | 20.000   |
| 69.0 | Glow Plug                          | number | JAPAN | 2800.000 |
| 70.0 | Grille radiator (black) Show       | number | JAPAN | 25.000   |
| 71.0 | Grille Radiator (Chrompated)       | number | JAPAN | 8500.000 |
| 72.0 | Hand Brake Cable (Front)           | number | JAPAN | 1750.000 |
| 73.0 | Hand Brake Cable (Rear)            | number | JAPAN | 3800.000 |
| 74.0 | Head and Rotor                     | number | JAPAN | 90.000   |
| 75.0 | Head Gasket                        | number | JAPAN | 3500.000 |
| 76.0 | Head Lamp 3 pin                    | number | JAPAN | 180.000  |
| 77.0 | Head Lamp Assembly                 | number | JAPAN | 4500.000 |
| 78.0 | Horn                               | number | JAPAN | 850.000  |
| 79.0 | Indicator/Side Light Bulb          | number | JAPAN | 45.000   |
| 80.0 | Injector Nozzle                    | number | JAPAN | 1150.000 |
| 81.0 | Kilometer Cable                    | number | JAPAN | 5.000    |
| 82.0 | Kin Pin Bearing                    | number | JAPAN | 25.000   |
| 83.0 | Kinpin Sim                         | number | JAPAN | 25.000   |
| 84.0 | Lamp Assy Front Bumper LH          | number | JAPAN | 30.000   |
| 85.0 | Lamp Assy Front Bumper RH          | number | JAPAN | 30.000   |
| 86.0 | Lens Front Indicator/Side Light LH | number | JAPAN | 30.000   |
| 87.0 | Lens Front Indicator/Side Light RH | number | JAPAN | 30.000   |
| 88.0 | Link Rod Washer                    | number | JAPAN | 180.000  |
| 89.0 | Lifter Valve                       | number | JAPAN | 650.000  |
| 90.0 | Main Bearing Oil Seal              | number | JAPAN | 1450.000 |

|       |                             |        |       |           |
|-------|-----------------------------|--------|-------|-----------|
| 91.0  | Mirror LH/RH                | number | JAPAN | 4500.000  |
| 92.0  | Oil Filter                  | number | JAPAN | 550.000   |
| 93.0  | Oil Pump Gear Inner         | number | JAPAN | 60.000    |
| 94.0  | Oil Pump Gear Outer         | number | JAPAN | 60.000    |
| 95.0  | Oil Seal Cam Shaft          | number | JAPAN | 650.000   |
| 96.0  | Oil Seal Engine Rear        | number | JAPAN | 650.000   |
| 97.0  | Oil Seal Front Axle Inner   | number | JAPAN | 210.000   |
| 98.0  | Oil Seal Front Hub Outer    | number | JAPAN | 750.000   |
| 99.0  | Oil Seal Oil Axle Outer     | number | JAPAN | 450.000   |
| 100.0 | Oil Seal Rear Axle Inner    | number | JAPAN | 850.000   |
| 101.0 | Oil Seal Tail Pinion        | number | JAPAN | 850.000   |
| 102.0 | Oil Seal Valve Stem         | number | JAPAN | 50.000    |
| 103.0 | Piston Ring                 | number | JAPAN | 5500.000  |
| 104.0 | Power Steering Oil          | number | JAPAN | 550.000   |
| 105.0 | Power Steering Pump         | number | JAPAN | 0.000     |
| 106.0 | Pressure Plate              | number | JAPAN | 8800.000  |
| 107.0 | Pump Service Kit            | number | JAPAN | 420.000   |
| 108.0 | Radiator Assembly           | number | JAPAN | 17000.000 |
| 109.0 | Radiator Cap                | number | JAPAN | 450.000   |
| 110.0 | Rain Guard                  | number | JAPAN | 3800.000  |
| 111.0 | Rear View Mirror            | number | JAPAN | 1250.000  |
| 112.0 | Relay Glow Plug             | number | JAPAN | 350.000   |
| 113.0 | Release Bearing             | number | JAPAN | 2800.000  |
| 114.0 | Seal Oil Timing Gear Case   | number | JAPAN | 65.000    |
| 115.0 | Self Starter Armature       | number | JAPAN | 3500.000  |
| 116.0 | Shock Absorber              | number | JAPAN | 0.000     |
| 117.0 | Shock Absorber Bush (Front) | number | JAPAN | 120.000   |
| 118.0 | Shock Absorber Front        | number | JAPAN | 2800.000  |
| 119.0 | Shock Absorber Rear         | number | JAPAN | 2800.000  |
| 120.0 | Shock Bush Lower/Upper      | number | JAPAN | 120.000   |
| 121.0 | Shocker Washer              | number | JAPAN | 180.000   |

|       |                            |        |       |          |
|-------|----------------------------|--------|-------|----------|
| 122.0 | Silencer Assy              | number | JAPAN | 1200.000 |
| 123.0 | Silencer Pipe Holder Bush  | number | JAPAN | 650.000  |
| 124.0 | Solenoid Switch (Self)     | number | JAPAN | 20.000   |
| 125.0 | Spacer Rear Axle Bearing   | number | JAPAN | 25.000   |
| 126.0 | Spring Bush Front - Rubber | number | JAPAN | 180.000  |
| 127.0 | Spring Front Leaf 2nd      | number | JAPAN | 5.000    |
| 128.0 | Spring Front Leaf 3rd      | number | JAPAN | 5.000    |
| 129.0 | Spring Front Leaf 4th      | number | JAPAN | 5.000    |
| 130.0 | Spring Front Leaf 5th      | number | JAPAN | 5.000    |
| 131.0 | Spring Metal Bush          | number | JAPAN | 20.000   |
| 132.0 | Spring Front Leaf Main     | number | JAPAN | 5.000    |
| 133.0 | Spring Mountain            | number | JAPAN | 5.000    |
| 134.0 | Spring Rear Leaf 2nd       | number | JAPAN | 1800.000 |
| 135.0 | Spring Rear Leaf 3rd       | number | JAPAN | 1800.000 |
| 136.0 | Spring Rear Leaf 4th       | number | JAPAN | 1400.000 |
| 137.0 | Spring Rear Leaf 5th       | number | JAPAN | 1400.000 |
| 138.0 | Spring Rear Leaf Main      | number | JAPAN | 1800.000 |
| 139.0 | Stabilizer Link Bush       | number | JAPAN | 120.000  |
| 140.0 | Stabilizer Link Rod        | number | JAPAN | 1650.000 |
| 141.0 | Stablizer Bush D type      | number | JAPAN | 850.000  |
| 142.0 | Steering Damper            | number | JAPAN | 25.000   |
| 143.0 | Steering Knuckle Kit       | number | JAPAN | 35.000   |
| 144.0 | Steering Rack Assembly     | number | JAPAN | 25.000   |
| 145.0 | Steering Rod               | number | JAPAN | 125.000  |
| 146.0 | Steering Yoke              | number | JAPAN | 4500.000 |
| 147.0 | Suspension Arm Upper       | number | JAPAN | 7500.000 |
| 148.0 | Suspension Arm Lower       | number | JAPAN | 7500.000 |
| 149.0 | Thermostat Valve           | number | JAPAN | 1800.000 |
| 150.0 | Thrust Washer              | number | JAPAN | 650.000  |
| 151.0 | Tierod End                 | number | JAPAN | 2800.000 |
| 152.0 | Timing Belt                | number | JAPAN | 2800.000 |

|       |                                           |        |       |           |
|-------|-------------------------------------------|--------|-------|-----------|
| 153.0 | Top sharp oil seal                        | number | JAPAN | 650.000   |
| 154.0 | Valve Exhaust                             | number | JAPAN | 350.000   |
| 155.0 | Valve External                            | number | JAPAN | 350.000   |
| 156.0 | Valve Guide                               | number | JAPAN | 450.000   |
| 157.0 | Valve Inlet                               | number | JAPAN | 450.000   |
| 158.0 | Valve Inner                               | number | JAPAN | 450.000   |
| 159.0 | Valve Seal                                | number | JAPAN | 450.000   |
| 160.0 | Valve Stem                                | number | JAPAN | 450.000   |
| 161.0 | Voltage Regulator                         | number | JAPAN | 130.000   |
| 162.0 | Water Pump Assembly                       | number | JAPAN | 7600.000  |
| 163.0 | Wheel Drum                                | number | JAPAN | 9500.000  |
| 164.0 | Wheel Nut and Bolt (Front/Rear)           | number | JAPAN | 250.000   |
| 165.0 | Wind Shields Glass                        | number | JAPAN | 17500.000 |
| 166.0 | Wiper Arm                                 | number | JAPAN | 450.000   |
| 167.0 | Wiper Motor                               | number | JAPAN | 1250.000  |
| 168.0 | Wiper Blade                               | number | JAPAN | 950.000   |
| 169.0 | Wiper Tank Motor                          | number | JAPAN | 650.000   |
| (II)  | <b>PART 2: Extra Accessories</b>          |        |       |           |
| 1.0   | Brake Oil Dot 3 (350 ml)                  | number | JAPAN | 550.000   |
| 2.0   | Anabond Gum                               | number | JAPAN | 90.000    |
| 3.0   | Cloth                                     | number | JAPAN | 10.000    |
| 4.0   | Coolant (per liter)                       | liter  | JAPAN | 260.000   |
| 5.0   | Dash Board Polish                         | number | JAPAN | 350.000   |
| 6.0   | Distilled Water                           | number | JAPAN | 45.000    |
| 7.0   | Engine Oil                                | number | JAPAN | 400.000   |
| 8.0   | Gear Box Oil Seal                         | number | JAPAN | 1250.000  |
| 9.0   | Gear Oil                                  | number | JAPAN | 300.000   |
| 10.0  | Grease                                    | number | JAPAN | 300.000   |
| 11.0  | Power Steering Oil                        | number | JAPAN | 550.000   |
| 12.0  | Rope                                      | number | JAPAN | 220.000   |
| 13.0  | Tail and Pinum Gear (Set) (4 Wheel) Front | number | JAPAN | 250.000   |

|       |                                         |        |                         |          |
|-------|-----------------------------------------|--------|-------------------------|----------|
| 14.0  | Disel Filter                            | number | JAPAN                   | 0.000    |
| 15.0  | Seat Cover (Set)                        | number | LUNG TEN<br>AUTOMOBILES | 8500.000 |
| (III) | <b>PART 3: Labour Charges (General)</b> |        |                         |          |
| 1.0   | Water Servicing and Air Servicing       | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 2.0   | Air Filter changing                     | number | LUNG TEN<br>AUTOMOBILES | 30.000   |
| 3.0   | Cam Shaft Oil Seal changing             | number | LUNG TEN<br>AUTOMOBILES | 350.000  |
| 4.0   | Crank Shaft Grinding                    | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 5.0   | Engine Block Boring                     | number | LUNG TEN<br>AUTOMOBILES | 2500.000 |
| 6.0   | Engine Cleaning                         | number | LUNG TEN<br>AUTOMOBILES | 10.000   |
| 7.0   | Engine Head Removing and Refitting      | number | LUNG TEN<br>AUTOMOBILES | 2500.000 |
| 8.0   | Engine Oil & Filter changing            | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 9.0   | Engine Overhauling 4 Cylinder Engine    | number | LUNG TEN<br>AUTOMOBILES | 2500.000 |
| 10.0  | Engine Overhauling 6 Cylinder Engine    | number | LUNG TEN<br>AUTOMOBILES | 0.000    |
| 11.0  | Engine Turning                          | number | LUNG TEN<br>AUTOMOBILES | 200.000  |
| 12.0  | FIT Overhauling                         | number | LUNG TEN<br>AUTOMOBILES | 1250.000 |
| 13.0  | Fuel Filter changing                    | number | LUNG TEN<br>AUTOMOBILES | 150.000  |
| 14.0  | Glow Plug changing                      | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 15.0  | Head Gasket changing                    | number | LUNG TEN<br>AUTOMOBILES | 1500.000 |
| 16.0  | Main Bearing Oil Seal changing          | number | LUNG TEN<br>AUTOMOBILES | 500.000  |
| 17.0  | Oil Pressure Switch changing            | number | LUNG TEN<br>AUTOMOBILES | 100.000  |

|      |                                                   |        |                         |          |
|------|---------------------------------------------------|--------|-------------------------|----------|
| 18.0 | Oil Pump Gear changing                            | number | LUNG TEN<br>AUTOMOBILES | 100.000  |
| 19.0 | Piston Ring changing                              | number | LUNG TEN<br>AUTOMOBILES | 650.000  |
| 20.0 | Radiator Servicing (Removing & Refetting)         | number | LUNG TEN<br>AUTOMOBILES | 1250.000 |
| 21.0 | Replacement of Radiator Hose                      | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 22.0 | Replacement of Thermostat Valve                   | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 23.0 | Replacement of Fan Belt                           | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 24.0 | Replacement of Injector Nozzle                    | number | LUNG TEN<br>AUTOMOBILES | 150.000  |
| 25.0 | Spark Plug changing or Servicing each             | number | LUNG TEN<br>AUTOMOBILES | 10.000   |
| 26.0 | Tappet Adjustment                                 | number | LUNG TEN<br>AUTOMOBILES | 145.000  |
| 27.0 | Tappet Cover Gasket changing                      | number | LUNG TEN<br>AUTOMOBILES | 950.000  |
| 28.0 | Timing Belt changing                              | number | LUNG TEN<br>AUTOMOBILES | 950.000  |
| 29.0 | Timing Gear Cover Oil Seal changing               | number | LUNG TEN<br>AUTOMOBILES | 950.000  |
| 30.0 | Valve Facing each valve                           | number | LUNG TEN<br>AUTOMOBILES | 125.000  |
| 31.0 | Water Pump overhauling                            | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| (VI) | <b>PART 4: Labour Charges (Electrical System)</b> |        |                         |          |
| 1.0  | Alternator Removing and Refitting/Overhauling     | number | LUNG TEN<br>AUTOMOBILES | 650.000  |
| 2.0  | Alternator Repairing                              | number | LUNG TEN<br>AUTOMOBILES | 650.000  |
| 3.0  | Back Light changing each                          | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 4.0  | Battery changing                                  | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 5.0  | C.B Point changing                                | number | LUNG TEN<br>AUTOMOBILES | 250.000  |

|      |                                     |        |                         |          |
|------|-------------------------------------|--------|-------------------------|----------|
| 6.0  | changing of Head Light Bulb         | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 7.0  | Complete Electrical Wire Check Up   | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 8.0  | Cut Out Adjustment                  | number | LUNG TEN<br>AUTOMOBILES | 350.000  |
| 9.0  | Dynamo Armature Rewinding           | number | LUNG TEN<br>AUTOMOBILES | 150.000  |
| 10.0 | Dynamo Overhauling                  | number | LUNG TEN<br>AUTOMOBILES | 1250.000 |
| 11.0 | Fog Light New Fitting               | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 12.0 | Head Light Bulb changing each       | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 13.0 | Head Light changing each            | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 14.0 | Horn Adjustment/Fitting             | number | LUNG TEN<br>AUTOMOBILES | 150.000  |
| 15.0 | Ignition Coil changing              | number | LUNG TEN<br>AUTOMOBILES | 35.000   |
| 16.0 | Incicator Assembly changing each    | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 17.0 | Indicator Bulb changing             | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 18.0 | Indicator Glass changing each       | number | LUNG TEN<br>AUTOMOBILES | 30.000   |
| 19.0 | Replacement of Electrical Switches  | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 20.0 | Replacement of Relays               | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 21.0 | Roof Lamp Bulb changing             | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 22.0 | Self Armature Rewinding             | number | LUNG TEN<br>AUTOMOBILES | 380.000  |
| 23.0 | Self Starter Overhauling            | number | LUNG TEN<br>AUTOMOBILES | 1250.000 |
| 24.0 | Self Starter Removing and Refitting | number | LUNG TEN<br>AUTOMOBILES | 450.000  |

|      |                                                  |        |                         |          |
|------|--------------------------------------------------|--------|-------------------------|----------|
| 25.0 | Self Starter Repairing                           | number | LUNG TEN<br>AUTOMOBILES | 1250.000 |
| 26.0 | Side Light Fitting                               | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 27.0 | Wiper Arm and Blade changing                     | number | LUNG TEN<br>AUTOMOBILES | 20.000   |
| (V)  | <b>PART 5: Labour Charges (Steering Portion)</b> |        |                         |          |
| 1.0  | Kingpin Overhauling (one side)                   | number | LUNG TEN<br>AUTOMOBILES | 20.000   |
| 2.0  | Knuckle Oil Sealing changing                     | number | LUNG TEN<br>AUTOMOBILES | 20.000   |
| 3.0  | Power Steering Overhauling                       | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 4.0  | Replacement of Pitman Arm                        | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 5.0  | Steering Box Overhauling                         | number | LUNG TEN<br>AUTOMOBILES | 550.000  |
| 6.0  | Steering Yoke changing                           | number | LUNG TEN<br>AUTOMOBILES | 350.000  |
| 7.0  | Tid Rod End changing                             | number | LUNG TEN<br>AUTOMOBILES | 350.000  |
| 8.0  | Tube Repairing/Patching                          | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 9.0  | Tyre Opening and Fitting                         | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 10.0 | Wheel Alignment                                  | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| (VI) | PART 6: Labour Charges (Transmission Portion)    | NA     | LUNG TEN<br>AUTOMOBILES | 0.000    |
| 1.0  | Removing & Fitting of Spring Assy                | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 2.0  | Centre Bearng changing                           | number | LUNG TEN<br>AUTOMOBILES | 150.000  |
| 3.0  | Clutch Master Cylinder Kit changing              | number | LUNG TEN<br>AUTOMOBILES | 200.000  |
| 4.0  | Clutch Master Cylinder Assembly changing         | number | LUNG TEN<br>AUTOMOBILES | 200.000  |
| 5.0  | Clutch Plate changing                            | number | LUNG TEN<br>AUTOMOBILES | 1200.000 |

|      |                                               |        |                         |          |
|------|-----------------------------------------------|--------|-------------------------|----------|
| 6.0  | Cross Bearing Replacement each                | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 7.0  | Crown and Tail Fitting                        | number | LUNG TEN<br>AUTOMOBILES | 850.000  |
| 8.0  | Differentail Overhauling/Remvoing & Refitting | number | LUNG TEN<br>AUTOMOBILES | 850.000  |
| 9.0  | Fly Wheel Bearing changing                    | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 10.0 | Front Axle Oil Seal changing each wheel       | number | LUNG TEN<br>AUTOMOBILES | 300.000  |
| 11.0 | Front Hub Oil Seal changing each wheel        | number | LUNG TEN<br>AUTOMOBILES | 300.000  |
| 12.0 | Front Wheel Bearing changing                  | number | LUNG TEN<br>AUTOMOBILES | 300.000  |
| 13.0 | Gear Box Overhauling                          | number | LUNG TEN<br>AUTOMOBILES | 1500.000 |
| 14.0 | Gear Oil changing                             | number | LUNG TEN<br>AUTOMOBILES | 200.000  |
| 15.0 | Nipple Greasing with Grease                   | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 16.0 | Hubs Greasing per wheel                       | number | LUNG TEN<br>AUTOMOBILES | 20.000   |
| 17.0 | Knuckle Oil changing                          | number | LUNG TEN<br>AUTOMOBILES | 20.000   |
| 18.0 | Pressure Plate changing                       | number | LUNG TEN<br>AUTOMOBILES | 1500.000 |
| 19.0 | Propeller Shaft Bolt Replacement              | number | LUNG TEN<br>AUTOMOBILES | 280.000  |
| 20.0 | Properller Shaft Cross Bearing changing each  | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 21.0 | Rear Axle Oil Seal changing and Greasing each | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 22.0 | Rear Hub Oil Seal changing each wheel         | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 23.0 | Release Bearing changing                      | number | LUNG TEN<br>AUTOMOBILES | 1200.000 |
| 24.0 | Gear Box removing and refitting               | number | LUNG TEN<br>AUTOMOBILES | 2500.000 |

|       |                                               |        |                         |         |
|-------|-----------------------------------------------|--------|-------------------------|---------|
| 25.0  | Spring Bush changing complete                 | number | LUNG TEN<br>AUTOMOBILES | 500.000 |
| 26.0  | Spring Leafs changing                         | number | LUNG TEN<br>AUTOMOBILES | 450.000 |
| 27.0  | Tail Pinion Bearing changing                  | number | LUNG TEN<br>AUTOMOBILES | 350.000 |
| 28.0  | Tail Pinion Oil Seal changing                 | number | LUNG TEN<br>AUTOMOBILES | 350.000 |
| 29.0  | Wheel Bolt changing each wheel                | number | LUNG TEN<br>AUTOMOBILES | 250.000 |
| (VII) | <b>PART 7: Labour Charges (Brake Portion)</b> |        |                         |         |
| 1.0   | Adjustment of brake (one each)                | number | LUNG TEN<br>AUTOMOBILES | 150.000 |
| 2.0   | Brake Booster Assembly changing               | number | LUNG TEN<br>AUTOMOBILES | 350.000 |
| 3.0   | Brake Booster Kit changing                    | number | LUNG TEN<br>AUTOMOBILES | 250.000 |
| 4.0   | Brake Disc removing and refitting             | number | LUNG TEN<br>AUTOMOBILES | 200.000 |
| 5.0   | Brake Disc turining/ facing                   | number | LUNG TEN<br>AUTOMOBILES | 950.000 |
| 6.0   | Brake Drum turning                            | number | LUNG TEN<br>AUTOMOBILES | 950.000 |
| 7.0   | Brake Linning changing                        | number | LUNG TEN<br>AUTOMOBILES | 10.000  |
| 8.0   | Brake Pad changing (1 side)                   | number | LUNG TEN<br>AUTOMOBILES | 200.000 |
| 9.0   | Brake Servicing each wheel                    | number | LUNG TEN<br>AUTOMOBILES | 200.000 |
| 10.0  | Brake Shoe changing rear wheel                | number | LUNG TEN<br>AUTOMOBILES | 200.000 |
| 11.0  | Brake Master Cylinder changing                | number | LUNG TEN<br>AUTOMOBILES | 350.000 |
| 12.0  | Brake Master Cylinder repair kit changing     | number | LUNG TEN<br>AUTOMOBILES | 250.000 |
| 13.0  | Front Brake Calpier Kit changing              | number | LUNG TEN<br>AUTOMOBILES | 150.000 |
| 14.0  | Gas Welding (per inch)                        | number | LUNG TEN<br>AUTOMOBILES | 100.000 |

|        |                                                   |        |                         |          |
|--------|---------------------------------------------------|--------|-------------------------|----------|
| 15.0   | Hoot Stitching                                    | number | LUNG TEN<br>AUTOMOBILES | 350.000  |
| 16.0   | Master Cylinder Assembly changing                 | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 17.0   | Master Cylinder Kit changing                      | number | LUNG TEN<br>AUTOMOBILES | 50.000   |
| 18.0   | Number Plate Writing                              | number | LUNG TEN<br>AUTOMOBILES | 400.000  |
| 19.0   | Wheel Cyclinder                                   | number | LUNG TEN<br>AUTOMOBILES | 3800.000 |
| 20.0   | W.C Kit changing each wheel front                 | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 21.0   | Wheel Bearing changing and fitting                | number | LUNG TEN<br>AUTOMOBILES | 150.000  |
| 22.0   | Wheel Bearing Rear changing                       | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 23.0   | Break Light Assymbly                              | number | LUNG TEN<br>AUTOMOBILES | 4800.000 |
| (VIII) | <b>PART 8: Labour Charges (Suspension System)</b> |        |                         |          |
| 1.0    | Coil Spring changing                              | number | LUNG TEN<br>AUTOMOBILES | 20.000   |
| 2.0    | Complete Spring bush changing                     | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 3.0    | Shacker Plate/Pin changing each                   | number | LUNG TEN<br>AUTOMOBILES | 150.000  |
| 4.0    | Shackle Absorber Mounting chaging                 | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 5.0    | Shock Absorber Bush changing                      | number | LUNG TEN<br>AUTOMOBILES | 80.000   |
| 6.0    | Shock Absorber changing each (front)              | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 7.0    | Shock Absorber changing each (rear)               | number | LUNG TEN<br>AUTOMOBILES | 250.000  |
| 8.0    | Spring Leaf changing (each spring)                | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 9.0    | Spring rearranging                                | number | LUNG TEN<br>AUTOMOBILES | 450.000  |
| 10.0   | Stablizer Bush changing each                      | number | LUNG TEN<br>AUTOMOBILES | 150.000  |

|      |                                                |        |                         |         |
|------|------------------------------------------------|--------|-------------------------|---------|
| (IX) | <b>PART 9: Labour Charges (Exhaust System)</b> |        |                         |         |
| 1.0  | Silencer Brake/Mounting changing               | number | LUNG TEN<br>AUTOMOBILES | 35.000  |
| 2.0  | Silencer Box removing and refitting            | number | LUNG TEN<br>AUTOMOBILES | 100.000 |

**Contact Detail:**

| Sl. No. | List of Bidders                     | Contact No                    | Email Address                                                    |
|---------|-------------------------------------|-------------------------------|------------------------------------------------------------------|
| 1       | <a href="#">Lungten Automobiles</a> | +975-17652636/ +975-02-351704 | <a href="mailto:lungtenauto@yahoo.com">lungtenauto@yahoo.com</a> |