

| Line Item No. | Description of Item | Unit of Measurement | Country of Origin | Amount |
|---------------|---------------------------------|---------------------|-------------------|----------|
| A | HIACE BUS | | | |
| (I) | PART 1: Vehicle Parts | | | |
| 1.0 | Air Filter | number | THAILAND | 2800.000 |
| 2.0 | Acelater Cable | number | THAILAND | 20.000 |
| 3.0 | Arm Bush Lower | number | THAILAND | 1800.000 |
| 4.0 | Arm Bush Upper | number | THAILAND | 1800.000 |
| 5.0 | Arm Steering Knuckle LH/RH | number | THAILAND | 250.000 |
| 6.0 | Arm Sub-Assy Pitman | number | THAILAND | 400.000 |
| 7.0 | Axle Cone (Rear) | number | THAILAND | 1800.000 |
| 8.0 | Axel Oil Seal | number | THAILAND | 750.000 |
| 9.0 | Axel Packing | number | THAILAND | 100.000 |
| 10.0 | Back Light Bulb (Single Point) | number | THAILAND | 45.000 |
| 11.0 | Ball Joint Upper | number | THAILAND | 3500.000 |
| 12.0 | Ball Joint Lower | number | THAILAND | 3500.000 |
| 13.0 | Battery | number | THAILAND | 8500.000 |
| 14.0 | Bearing center support | number | THAILAND | 250.000 |
| 15.0 | Bearing Diff. Inner | number | THAILAND | 725.000 |
| 16.0 | Bearing Diff. Side Gear | number | THAILAND | 950.000 |
| 17.0 | Bearing Front Wheel Inner | number | THAILAND | 8800.000 |
| 18.0 | Bearing Front Wheel Outer | number | THAILAND | 0.000 |
| 19.0 | Bearing Rear Axle/Wheel | number | THAILAND | 3800.000 |
| 20.0 | Bearing Set Connecting Rod | number | THAILAND | 1100.000 |
| 21.0 | Bearing Set Crankshaft | number | THAILAND | 650.000 |
| 22.0 | Bearing Tail Pinion Outer | number | THAILAND | 450.000 |
| 23.0 | Brake Booster Assy | number | THAILAND | 8500.000 |
| 24.0 | Brake Light Bulb (Double Point) | number | THAILAND | 45.000 |
| 25.0 | Brake Pad | number | THAILAND | 8500.000 |
| 26.0 | Brake Shoe Rear | number | THAILAND | 5800.000 |

| | | | | |
|------|-------------------------------------|--------|----------|-----------|
| 27.0 | Bumper Light Assy (Front) | number | THAILAND | 100.000 |
| 28.0 | Bush Front Suspension (Lower LH) | number | THAILAND | 10.000 |
| 29.0 | Bush Front Suspension)Lower RH) | number | THAILAND | 10.000 |
| 30.0 | Bush Front Suspension (Upper RH/LH) | number | THAILAND | 10.000 |
| 31.0 | Bush Rear Stabilizer | number | THAILAND | 50.000 |
| 32.0 | Cam Shaft Bearing | number | THAILAND | 450.000 |
| 33.0 | Camp Bearing | number | THAILAND | 110.000 |
| 34.0 | Cap Assy. Fuel Filter | number | THAILAND | 1650.000 |
| 35.0 | Center Bolt | number | THAILAND | 180.000 |
| 36.0 | Clutch Plate | number | THAILAND | 9500.000 |
| 37.0 | Clutch Release Bearing | number | THAILAND | 0.000 |
| 38.0 | Bendix Pinion | number | THAILAND | 6800.000 |
| 40.0 | Cross Bearing | number | THAILAND | 3800.000 |
| 41.0 | CV Joint Boot (Outer) | number | THAILAND | 1200.000 |
| 42.0 | CV Joint Boot (Inner) | number | THAILAND | 2400.000 |
| 43.0 | Cylinder Assy Brake Master | number | THAILAND | 11500.000 |
| 44.0 | Cylinder Assy Clutch Master | number | THAILAND | 5800.000 |
| 45.0 | Cylinder Kit Brake Master | number | THAILAND | 350.000 |
| 46.0 | Cylinder Kit Clutch Master | number | THAILAND | 40.000 |
| 47.0 | Cylinder Kit Front Disc Brake | number | THAILAND | 25.000 |
| 48.0 | Cylinder Kit Rear Wheel | number | THAILAND | 100.000 |
| 49.0 | Deliver Valve | number | THAILAND | 100.000 |
| 50.0 | Diesel Filter | number | THAILAND | 1150.000 |
| 51.0 | Dust Guard | number | THAILAND | 2000.000 |
| 52.0 | End Sub Assy Tie Rod (LH) | number | THAILAND | 3800.000 |
| 53.0 | End Sub Assy Tie Rod (RH) | number | THAILAND | 3800.000 |
| 54.0 | Engine Linner | number | THAILAND | 3500.000 |
| 55.0 | Fan Belt | number | THAILAND | 2800.000 |
| 56.0 | Fan Sub-Assembly | number | THAILAND | 200.000 |
| 57.0 | Fly Ring Gear | number | THAILAND | 580.000 |
| 58.0 | Fog Lamp | number | THAILAND | 3500.000 |

| | | | | |
|------|------------------------------------|--------|----------|-----------|
| 59.0 | Foot Stand | number | THAILAND | 4500.000 |
| 60.0 | Four Wheel Bearing | number | THAILAND | 150.000 |
| 61.0 | Front Wheel Check Nut | number | THAILAND | 250.000 |
| 62.0 | Front Wheel Checknut Lock | number | THAILAND | 250.000 |
| 63.0 | Fuel Filter | number | THAILAND | 1150.000 |
| 64.0 | Fuel Tank | number | THAILAND | 120.000 |
| 65.0 | Gasket Engine Overhaul | number | THAILAND | 7500.000 |
| 66.0 | Glass Back Light Assy LH/RH | number | THAILAND | 35.000 |
| 67.0 | Glass Back Light LH/RH | number | THAILAND | 35.000 |
| 68.0 | Glass Front Indicator LH/RH | number | THAILAND | 20.000 |
| 69.0 | Glow Plug | number | THAILAND | 2800.000 |
| 70.0 | Grille radiator (black) Show | number | THAILAND | 25.000 |
| 71.0 | Grille Radiator (Chrompated) | number | THAILAND | 8500.000 |
| 72.0 | Hand Brake Cable (Front) | number | THAILAND | 2900.000 |
| 73.0 | Hand Brake Cable (Rear) | number | THAILAND | 4500.000 |
| 74.0 | Head and Rotor | number | THAILAND | 90.000 |
| 75.0 | Head Gasket | number | THAILAND | 3500.000 |
| 76.0 | Head Lamp 3 pin | number | THAILAND | 180.000 |
| 77.0 | Head Lamp Assembly | number | THAILAND | 8500.000 |
| 78.0 | Horn | number | THAILAND | 850.000 |
| 79.0 | Indicator/Side Light Bulb | number | THAILAND | 45.000 |
| 80.0 | Injector Nozzle | number | THAILAND | 28000.000 |
| 81.0 | Kilometer Cable | number | THAILAND | 5.000 |
| 82.0 | Kin Pin Bearing | number | THAILAND | 25.000 |
| 83.0 | Kinpin Sim | number | THAILAND | 25.000 |
| 84.0 | Lamp Assy Front Bumper LH | number | THAILAND | 30.000 |
| 85.0 | Lamp Assy Front Bumper RH | number | THAILAND | 30.000 |
| 86.0 | Lens Front Indicator/Side Light LH | number | THAILAND | 30.000 |
| 87.0 | Lens Front Indicator/Side Light RH | number | THAILAND | 30.000 |
| 88.0 | Link Rod Washer | number | THAILAND | 180.000 |
| 89.0 | Lifter Valve | number | THAILAND | 650.000 |

| | | | | |
|-------|-----------------------------|--------|----------|-----------|
| 90.0 | Main Bearing Oil Seal | number | THAILAND | 1450.000 |
| 91.0 | Mirror LH/RH | number | THAILAND | 9800.000 |
| 92.0 | Oil Filter | number | THAILAND | 850.000 |
| 93.0 | Oil Pump Gear Inner | number | THAILAND | 60.000 |
| 94.0 | Oil Pump Gear Outer | number | THAILAND | 60.000 |
| 95.0 | Oil Seal Cam Shaft | number | THAILAND | 650.000 |
| 96.0 | Oil Seal Engine Rear | number | THAILAND | 650.000 |
| 97.0 | Oil Seal Front Axle Inner | number | THAILAND | 210.000 |
| 98.0 | Oil Seal Front Hub Outer | number | THAILAND | 650.000 |
| 99.0 | Oil Seal Oil Axle Outer | number | THAILAND | 450.000 |
| 100.0 | Oil Seal Rear Axle Inner | number | THAILAND | 850.000 |
| 101.0 | Oil Seal Tail Pinion | number | THAILAND | 850.000 |
| 102.0 | Oil Seal Valve Stem | number | THAILAND | 50.000 |
| 103.0 | Piston Ring | number | THAILAND | 7500.000 |
| 104.0 | Power Steering Oil | number | THAILAND | 550.000 |
| 105.0 | Power Steering Pump | number | THAILAND | 0.000 |
| 106.0 | Pressure Plate | number | THAILAND | 10800.000 |
| 107.0 | Pump Service Kit | number | THAILAND | 420.000 |
| 108.0 | Radiator Assembly | number | THAILAND | 17000.000 |
| 109.0 | Radiator Cap | number | THAILAND | 450.000 |
| 110.0 | Rain Guard | number | THAILAND | 3800.000 |
| 111.0 | Rear View Mirror | number | THAILAND | 1250.000 |
| 112.0 | Relay Glow Plug | number | THAILAND | 350.000 |
| 113.0 | Release Bearing | number | THAILAND | 3500.000 |
| 114.0 | Seal Oil Timing Gear Case | number | THAILAND | 65.000 |
| 115.0 | Self Starter Armature | number | THAILAND | 3500.000 |
| 116.0 | Shock Absorber | number | THAILAND | 0.000 |
| 117.0 | Shock Absorber Bush (Front) | number | THAILAND | 120.000 |
| 118.0 | Shock Absorber Front | number | THAILAND | 5800.000 |
| 119.0 | Shock Absorber Rear | number | THAILAND | 2800.000 |
| 120.0 | Shock Bush Lower/Upper | number | THAILAND | 120.000 |

| | | | | |
|-------|----------------------------|--------|----------|-----------|
| 121.0 | Shocker Washer | number | THAILAND | 180.000 |
| 122.0 | Silencer Assy | number | THAILAND | 5500.000 |
| 123.0 | Silencer Pipe Holder Bush | number | THAILAND | 650.000 |
| 124.0 | Solenoid Switch (Self) | number | THAILAND | 20.000 |
| 125.0 | Spacer Rear Axle Bearing | number | THAILAND | 3500.000 |
| 126.0 | Spring Bush Front - Rubber | number | THAILAND | 180.000 |
| 127.0 | Spring Front Leaf 2nd | number | THAILAND | 5.000 |
| 128.0 | Spring Front Leaf 3rd | number | THAILAND | 5.000 |
| 129.0 | Spring Front Leaf 4th | number | THAILAND | 5.000 |
| 130.0 | Spring Front Leaf 5th | number | THAILAND | 5.000 |
| 131.0 | Spring Metal Bush | number | THAILAND | 20.000 |
| 132.0 | Spring Front Leaf Main | number | THAILAND | 5.000 |
| 133.0 | Spring Mountain | number | THAILAND | 5.000 |
| 134.0 | Spring Rear Leaf 2nd | number | THAILAND | 20.000 |
| 135.0 | Spring Rear Leaf 3rd | number | THAILAND | 20.000 |
| 136.0 | Spring Rear Leaf 4th | number | THAILAND | 20.000 |
| 137.0 | Spring Rear Leaf 5th | number | THAILAND | 20.000 |
| 138.0 | Spring Rear Leaf Main | number | THAILAND | 20.000 |
| 139.0 | Stabilizer Link Bush | number | THAILAND | 120.000 |
| 140.0 | Stabilizer Link Rod | number | THAILAND | 3800.000 |
| 141.0 | Stablizer Bush D type | number | THAILAND | 1250.000 |
| 142.0 | Steering Damper | number | THAILAND | 25.000 |
| 143.0 | Steering Knuckle Kit | number | THAILAND | 35.000 |
| 144.0 | Steering Rack Assembly | number | THAILAND | 65000.000 |
| 145.0 | Steering Rod | number | THAILAND | 125.000 |
| 146.0 | Steering Yoke | number | THAILAND | 4500.000 |
| 147.0 | Suspension Arm Upper | number | THAILAND | 7500.000 |
| 148.0 | Suspension Arm Lower | number | THAILAND | 7500.000 |
| 149.0 | Thermostat Valve | number | THAILAND | 1800.000 |
| 150.0 | Thrust Washer | number | THAILAND | 650.000 |
| 151.0 | Tierod End | number | THAILAND | 3800.000 |

| | | | | |
|-------|----------------------------------|--------|----------|-----------|
| 152.0 | Timing Belt | number | THAILAND | 3800.000 |
| 153.0 | Top sharp oil seal | number | THAILAND | 650.000 |
| 154.0 | Valve Exhaust | number | THAILAND | 350.000 |
| 155.0 | Valve External | number | THAILAND | 350.000 |
| 156.0 | Valve Guide | number | THAILAND | 450.000 |
| 157.0 | Valve Inlet | number | THAILAND | 450.000 |
| 158.0 | Valve Inner | number | THAILAND | 450.000 |
| 159.0 | Valve Seal | number | THAILAND | 450.000 |
| 160.0 | Valve Stem | number | THAILAND | 450.000 |
| 161.0 | Voltage Regulator | number | THAILAND | 130.000 |
| 162.0 | Water Pump Assembly | number | THAILAND | 7600.000 |
| 163.0 | Wheel Drum | number | THAILAND | 9500.000 |
| 164.0 | Wheel Nut and Bolt (Front/Rear) | number | THAILAND | 250.000 |
| 165.0 | Wind Shields Glass | number | THAILAND | 17500.000 |
| 166.0 | Wiper Arm | number | THAILAND | 450.000 |
| 167.0 | Wiper Motor | number | THAILAND | 1250.000 |
| 168.0 | Wiper Blade | number | THAILAND | 950.000 |
| 169.0 | Wiper Tank Motor | number | THAILAND | 650.000 |
| (II) | PART 2: Extra Accessories | | | |
| 1.0 | Brake Oil Dot 3 (350 ml) | number | THAILAND | 550.000 |
| 2.0 | Anabond Gum | number | THAILAND | 90.000 |
| 3.0 | Cloth | number | THAILAND | 10.000 |
| 4.0 | Coolant (per liter) | liter | THAILAND | 260.000 |
| 5.0 | Dash Board Polish | number | THAILAND | 350.000 |
| 6.0 | Distilled Water | number | THAILAND | 45.000 |
| 7.0 | Engine Oil | number | THAILAND | 400.000 |
| 8.0 | Gear Box Oil Seal | number | THAILAND | 850.000 |
| 9.0 | Gear Oil | number | THAILAND | 300.000 |
| 10.0 | Grease | number | THAILAND | 300.000 |
| 11.0 | Power Steering Oil | number | THAILAND | 550.000 |
| 12.0 | Rope | number | THAILAND | 220.000 |

| | | | | |
|-------|---|--------|------------------------|----------|
| 13.0 | Tail and Pinum Gear (Set) (4 Wheel) Front | number | THAILAND | 250.000 |
| 14.0 | Disel Filter | number | THAILAND | 0.000 |
| 15.0 | Seat Cover (Set) | number | LUNGTEN AUTOMOBILES | 9500.000 |
| (III) | PART 3: Labour Charges (General) | | | |
| 1.0 | Water Servicing and Air Servicing | number | LUNGTEN AUTOMOBILES | 450.000 |
| 2.0 | Air Filter changing | number | LUNGTEN AUTOMOBILES | 30.000 |
| 3.0 | Cam Shaft Oil Seal changing | number | LUNGTEN AUTOMOBILES | 350.000 |
| 4.0 | Crank Shaft Grinding | number | LUNGTEN AUTOMOBILES | 450.000 |
| 5.0 | Engine Block Boring | number | LUNGTEN AUTOMOBILES | 2500.000 |
| 6.0 | Engine Cleaning | number | LUNGTEN AUTOMOBILES | 10.000 |
| 7.0 | Engine Head Removing and Refitting | number | LUNGTEN AUTOMOBILES | 2500.000 |
| 8.0 | Engine Oil & Filter changing | number | LUNGTEN AUTOMOBILES | 250.000 |
| 9.0 | Engine Overhauling 4 Cylinder Engine | number | LUNGTEN AUTOMOBILES | 2500.000 |
| 10.0 | Engine Overhauling 6 Cylinder Engine | number | LUNGTEN AUTOMOBILES | 0.000 |
| 11.0 | Engine Turning | number | LUNGTEN AUTOMOBILES | 250.000 |
| 12.0 | FIT Overhauling | number | LUNGTEN AUTOMOBILES | 1250.000 |
| 13.0 | Fuel Filter changing | number | LUNGTEN AUTOMOBILES | 15.000 |
| 14.0 | Glow Plug changing | number | LUNGTEN AUTOMOBILES | 250.000 |
| 15.0 | Head Gasket changing | number | LUNGTEN AUTOMOBILES | 1500.000 |
| 16.0 | Main Bearing Oil Seal changing | number | LUNGTEN AUTOMOBILES | 500.000 |
| 17.0 | Oil Pressure Switch changing | number | LUNGTEN AUTOMOBILES | 100.000 |

| | | | | |
|------|---|--------|------------------------|----------|
| 18.0 | Oil Pump Gear changing | number | LUNGTEN AUTOMOBILES | 100.000 |
| 19.0 | Piston Ring changing | number | LUNGTEN AUTOMOBILES | 650.000 |
| 20.0 | Radiator Servicing (Removing & Refetting) | number | LUNGTEN AUTOMOBILES | 1250.000 |
| 21.0 | Replacement of Radiator Hose | number | LUNGTEN AUTOMOBILES | 250.000 |
| 22.0 | Replacement of Thermostat Valve | number | LUNGTEN AUTOMOBILES | 250.000 |
| 23.0 | Replacement of Fan Belt | number | LUNGTEN AUTOMOBILES | 250.000 |
| 24.0 | Replacement of Injector Nozzle | number | LUNGTEN AUTOMOBILES | 650.000 |
| 25.0 | Spark Plug changing or Servicing each | number | LUNGTEN AUTOMOBILES | 10.000 |
| 26.0 | Tappet Adjustment | number | LUNGTEN AUTOMOBILES | 145.000 |
| 27.0 | Tappet Cover Gasket changing | number | LUNGTEN AUTOMOBILES | 950.000 |
| 28.0 | Timing Belt changing | number | LUNGTEN AUTOMOBILES | 950.000 |
| 29.0 | Timing Gear Cover Oil Seal changing | number | LUNGTEN AUTOMOBILES | 950.000 |
| 30.0 | Valve Facing each valve | number | LUNGTEN AUTOMOBILES | 125.000 |
| 31.0 | Water Pump overhauling | number | LUNGTEN AUTOMOBILES | 450.000 |
| (VI) | PART 4: Labour Charges (Electrical System) | number | LUNGTEN AUTOMOBILES | 0.000 |
| 1.0 | Alternator Removing and Refitting/Overhauling | number | LUNGTEN AUTOMOBILES | 650.000 |
| 2.0 | Alternator Repairing | number | LUNGTEN AUTOMOBILES | 650.000 |
| 3.0 | Back Light changing each | number | LUNGTEN AUTOMOBILES | 50.000 |
| 4.0 | Battery changing | number | LUNGTEN AUTOMOBILES | 50.000 |

| | | | | |
|------|------------------------------------|--------|------------------------|----------|
| 5.0 | C.B Point changing | number | LUNGTEN AUTOMOBILES | 250.000 |
| 6.0 | changing of Head Light Bulb | number | LUNGTEN AUTOMOBILES | 50.000 |
| 7.0 | Complete Electrical Wire Check Up | number | LUNGTEN AUTOMOBILES | 450.000 |
| 8.0 | Cut Out Adjustment | number | LUNGTEN AUTOMOBILES | 350.000 |
| 9.0 | Dynamo Armature Rewinding | number | LUNGTEN AUTOMOBILES | 250.000 |
| 10.0 | Dynamo Overhauling | number | LUNGTEN AUTOMOBILES | 1250.000 |
| 11.0 | Fog Light New Fitting | number | LUNGTEN AUTOMOBILES | 250.000 |
| 12.0 | Head Light Bulb changing each | number | LUNGTEN AUTOMOBILES | 50.000 |
| 13.0 | Head Light changing each | number | LUNGTEN AUTOMOBILES | 50.000 |
| 14.0 | Horn Adjustment/Fitting | number | LUNGTEN AUTOMOBILES | 150.000 |
| 15.0 | Ignition Coil changing | number | LUNGTEN AUTOMOBILES | 35.000 |
| 16.0 | Incicator Assembly changing each | number | LUNGTEN AUTOMOBILES | 50.000 |
| 17.0 | Indicator Bulb changing | number | LUNGTEN AUTOMOBILES | 50.000 |
| 18.0 | Indicator Glass changing each | number | LUNGTEN AUTOMOBILES | 30.000 |
| 19.0 | Replacement of Electrical Switches | number | LUNGTEN AUTOMOBILES | 250.000 |
| 20.0 | Replacement of Relays | number | LUNGTEN AUTOMOBILES | 250.000 |
| 21.0 | Roof Lamp Bulb changing | number | LUNGTEN AUTOMOBILES | 50.000 |
| 22.0 | Self Armature Rewinding | number | LUNGTEN AUTOMOBILES | 380.000 |
| 23.0 | Self Starter Overhauling | number | LUNGTEN AUTOMOBILES | 1250.000 |

| | | | | |
|------|--|--------|------------------------|----------|
| 24.0 | Self Starter Removing and Refitting | number | LUNGTEN AUTOMOBILES | 450.000 |
| 25.0 | Self Starter Repairing | number | LUNGTEN AUTOMOBILES | 1250.000 |
| 26.0 | Side Light Fitting | number | LUNGTEN AUTOMOBILES | 50.000 |
| 27.0 | Wiper Arm and Blade changing | number | LUNGTEN AUTOMOBILES | 20.000 |
| (V) | PART 5: Labour Charges (Steering Portion) | | | |
| 1.0 | Kingpin Overhauling (one side) | number | LUNGTEN AUTOMOBILES | 20.000 |
| 2.0 | Knuckle Oil Sealing changing | number | LUNGTEN AUTOMOBILES | 20.000 |
| 3.0 | Power Steering Overhauling | number | LUNGTEN AUTOMOBILES | 250.000 |
| 4.0 | Replacement of Pitman Arm | number | LUNGTEN AUTOMOBILES | 250.000 |
| 5.0 | Steering Box Overhauling | number | LUNGTEN AUTOMOBILES | 550.000 |
| 6.0 | Steering Yoke changing | number | LUNGTEN AUTOMOBILES | 350.000 |
| 7.0 | Tid Rod End changing | number | LUNGTEN AUTOMOBILES | 450.000 |
| 8.0 | Tube Repairing/Patching | number | LUNGTEN AUTOMOBILES | 250.000 |
| 9.0 | Tyre Opening and Fitting | number | LUNGTEN AUTOMOBILES | 250.000 |
| 10.0 | Wheel Alignment | number | LUNGTEN AUTOMOBILES | 450.000 |
| (VI) | PART 6: Labour Charges (Transmission Portion) | | | |
| 1.0 | Removing & Fitting of Spring Assy | number | LUNGTEN AUTOMOBILES | 450.000 |
| 2.0 | Centre Beairng changing | number | LUNGTEN AUTOMOBILES | 150.000 |
| 3.0 | Clutch Master Cylinder Kit changing | number | LUNGTEN AUTOMOBILES | 200.000 |
| 4.0 | Clutch Master Cylinder Assembly changing | number | LUNGTEN AUTOMOBILES | 200.000 |

| | | | | |
|------|---|--------|------------------------|----------|
| 5.0 | Clutch Plate changing | number | LUNGTEN AUTOMOBILES | 1200.000 |
| 6.0 | Cross Bearing Replacement each | number | LUNGTEN AUTOMOBILES | 250.000 |
| 7.0 | Crown and Tail Fitting | number | LUNGTEN AUTOMOBILES | 850.000 |
| 8.0 | Differentail Overhauling/Remvoing & Refitting | number | LUNGTEN AUTOMOBILES | 850.000 |
| 9.0 | Fly Wheel Bearing changing | number | LUNGTEN AUTOMOBILES | 250.000 |
| 10.0 | Front Axle Oil Seal changing each wheel | number | LUNGTEN AUTOMOBILES | 300.000 |
| 11.0 | Front Hub Oil Seal changing each wheel | number | LUNGTEN AUTOMOBILES | 300.000 |
| 12.0 | Front Wheel Bearing changing | number | LUNGTEN AUTOMOBILES | 300.000 |
| 13.0 | Gear Box Overhauling | number | LUNGTEN AUTOMOBILES | 1500.000 |
| 14.0 | Gear Oil changing | number | LUNGTEN AUTOMOBILES | 200.000 |
| 15.0 | Nipple Greasing with Grease | number | LUNGTEN AUTOMOBILES | 450.000 |
| 16.0 | Hubs Greasing per wheel | number | LUNGTEN AUTOMOBILES | 20.000 |
| 17.0 | Knuckle Oil changing | number | LUNGTEN AUTOMOBILES | 20.000 |
| 18.0 | Pressure Plate changing | number | LUNGTEN AUTOMOBILES | 1500.000 |
| 19.0 | Propeller Shaft Bolt Replacement | number | LUNGTEN AUTOMOBILES | 280.000 |
| 20.0 | Properller Shaft Cross Bearing changing each | number | LUNGTEN AUTOMOBILES | 250.000 |
| 21.0 | Rear Axle Oil Seal changing and Greasing each | number | LUNGTEN AUTOMOBILES | 250.000 |
| 22.0 | Rear Hub Oil Seal changing each wheel | number | LUNGTEN AUTOMOBILES | 250.000 |
| 23.0 | Release Bearing changing | number | LUNGTEN AUTOMOBILES | 1200.000 |

| | | | | |
|-------|---|--------|------------------------|----------|
| 24.0 | Gear Box removing and refitting | number | LUNGTEN AUTOMOBILES | 2500.000 |
| 25.0 | Spring Bush changing complete | number | LUNGTEN AUTOMOBILES | 500.000 |
| 26.0 | Spring Leafs changing | number | LUNGTEN AUTOMOBILES | 450.000 |
| 27.0 | Tail Pinion Bearing changing | number | LUNGTEN AUTOMOBILES | 350.000 |
| 28.0 | Tail Pinion Oil Seal changing | number | LUNGTEN AUTOMOBILES | 350.000 |
| 29.0 | Wheel Bolt changing each wheel | number | LUNGTEN AUTOMOBILES | 250.000 |
| (VII) | PART 7: Labour Charges (Brake Portion) | | | |
| 1.0 | Adjustment of brake (one each) | number | LUNGTEN AUTOMOBILES | 150.000 |
| 2.0 | Brake Booster Assembly changing | number | LUNGTEN AUTOMOBILES | 350.000 |
| 3.0 | Brake Booster Kit changing | number | LUNGTEN AUTOMOBILES | 250.000 |
| 4.0 | Brake Disc removing and refitting | number | LUNGTEN AUTOMOBILES | 200.000 |
| 5.0 | Brake Disc turning/ facing | number | LUNGTEN AUTOMOBILES | 950.000 |
| 6.0 | Brake Drum turning | number | LUNGTEN AUTOMOBILES | 950.000 |
| 7.0 | Brake Linning changing | number | LUNGTEN AUTOMOBILES | 10.000 |
| 8.0 | Brake Pad changing (1 side) | number | LUNGTEN AUTOMOBILES | 200.000 |
| 9.0 | Brake Servicing each wheel | number | LUNGTEN AUTOMOBILES | 200.000 |
| 10.0 | Brake Shoe changing rear wheel | number | LUNGTEN AUTOMOBILES | 200.000 |
| 11.0 | Brake Master Cylinder changing | number | LUNGTEN AUTOMOBILES | 350.000 |
| 12.0 | Brake Master Cylinder repair kit changing | number | LUNGTEN AUTOMOBILES | 250.000 |
| 13.0 | Front Brake Calpier Kit changing | number | LUNGTEN AUTOMOBILES | 150.000 |

| | | | | |
|--------|---|--------|------------------------|----------|
| 14.0 | Gas Welding (per inch) | number | LUNGTEN AUTOMOBILES | 100.000 |
| 15.0 | Hoot Stitching | number | LUNGTEN AUTOMOBILES | 350.000 |
| 16.0 | Master Cylinder Assembly changing | number | LUNGTEN AUTOMOBILES | 50.000 |
| 17.0 | Master Cylinder Kit changing | number | LUNGTEN AUTOMOBILES | 50.000 |
| 18.0 | Number Plate Writing | number | LUNGTEN AUTOMOBILES | 400.000 |
| 19.0 | Wheel Cyclinder | number | LUNGTEN AUTOMOBILES | 3800.000 |
| 20.0 | W.C Kit changing each wheel front | number | LUNGTEN AUTOMOBILES | 250.000 |
| 21.0 | Wheel Bearing changing and fitting | number | LUNGTEN AUTOMOBILES | 150.000 |
| 22.0 | Wheel Bearing Rear changing | number | LUNGTEN AUTOMOBILES | 250.000 |
| 23.0 | Break Light Assymlby | number | LUNGTEN AUTOMOBILES | 4800.000 |
| (VIII) | PART 8: Labour Charges (Suspension System) | | | |
| 1.0 | Coil Spring changing | number | LUNGTEN AUTOMOBILES | 20.000 |
| 2.0 | Complete Spring bush changing | number | LUNGTEN AUTOMOBILES | 20.000 |
| 3.0 | Shacker Plate/Pin changing each | number | LUNGTEN AUTOMOBILES | 150.000 |
| 4.0 | Shackle Absorber Mounting chaging | number | LUNGTEN AUTOMOBILES | 250.000 |
| 5.0 | Shock Absorber Bush changing | number | LUNGTEN AUTOMOBILES | 80.000 |
| 6.0 | Shock Absorber changing each (front) | number | LUNGTEN AUTOMOBILES | 450.000 |
| 7.0 | Shock Absorber changing each (rear) | number | LUNGTEN AUTOMOBILES | 250.000 |
| 8.0 | Spring Leaf changing (each spring) | number | LUNGTEN AUTOMOBILES | 450.000 |
| 9.0 | Spring rearranging | number | LUNGTEN AUTOMOBILES | 450.000 |

| | | | | |
|------|--|--------|-------------------------|---------|
| 10.0 | Stablizer Bush changing each | number | LUNG TEN AUTOMOBILES | 150.000 |
| (IX) | PART 9: Labour Charges (Exhaust System) | | | |
| 1.0 | Silencer Brake/Mounting changing | number | LUNG TEN AUTOMOBILES | 35.000 |
| 2.0 | Silencer Box removing and refitting | number | LUNG TEN AUTOMOBILES | 100.000 |

Contact Detail:

| Sl. No. | List of Bidders | Contact No | Email Address |
|---------|-------------------------------------|-------------------------------|--|
| 1 | Lungten Automobiles | +975-17652636/ +975-02-351704 | lungtenauto@yahoo.com |